

City of Baltimore Wet Weather Consent Decree Smoke and Dyed Water Testing Form		Page 1 of 4
Sewershed : Gwynn Falls	Company : <u>URS</u>	Date: 10/27/2008
Test to be Performed : Smoke : X Dyed Water :	Ground Condition : Dry : X Damp : Wet :	Supervisor : John Daly
Manhole ID: S04EE1009MH	Test ID: S1032-028007	Notifications (Residents, Fire, 311) : Yes



City of Baltimore Wet Weather Consent Decree Smoke and Dyed Water Testing Form		Page 2 of 4
Sewershed : Gwynn Falls	Company : <u>URS</u>	Date : 10/27/2008
Test to be Performed : Smoke : X Dyed Water :	Ground Condition : Dry : X Damp : Wet :	Supervisor : John Daly
Manhole ID: S04EE1009MH	Test ID: S1032-028007	Notifications (Residents, Fire, 311) : Yes

ID



Location: N/A; Type: Catch Basin; Smoke: Light; Status: Public ROW


Landscape



Defect



ID



Location: N/A; Type: Catch Basin; Smoke: Light; Status: Public ROW

Landscape



Defect



City of Baltimore Wet Weather Consent Decree Smoke and Dyed Water Testing Form		Page 3 of 4
Sewershed : Gwynn Falls	Company : <u>URS</u>	Date : 10/27/2008
Test to be Performed : Smoke : X Dyed Water :	Ground Condition : Dry : X Damp : Wet :	Supervisor : John Daly
Manhole ID: S04EE1009MH	Test ID: S1032-028007	Notifications (Residents, Fire, 311) : Yes

ID



Location: N/A; Type: Catch Basin; Smoke: Light; Status: Public ROW


Landscape



Defect



ID



 $Location: N/A; \ Type: \ Service \ Lateral; \ Smoke: \ Light;$

Status: Public ROW

Landscape




Defect



City of Baltimore Wet Weather Consent Decree Smoke and Dyed Water Testing Form		Page 4 of 4
Sewershed : Gwynn Falls	Company : <u>URS</u>	Date : 10/27/2008
Test to be Performed : Smoke : X Dyed Water :	Ground Condition : Dry : X Damp : Wet :	Supervisor : John Daly
Manhole ID: S04EE1009MH	Test ID: S1032-028007	Notifications (Residents, Fire, 311) : Yes

ID



Location: N/A; Type: Catch Basin; Smoke:

Medium; Status: Public ROW

Landscape



Defect



ID



Location: N/A; Type: Catch Basin; Smoke: Heavy;

Status: Public ROW

Landscape



Defect

